

Inspection Record Report

Part Number & Part Name: LHE6118

Inspection referred document: LHE6118检验文件

Inspection time: 2023-11-27

Inspection step:

| Inspection item | Inspection/Testing Criteria | Inspection method | Inspection result | Judgment | Remark |
|---|-----------------------------|-------------------|-------------------|----------|--------|
| 1.Cosmetic Inspection | | | | | |
| Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap. | | Visual check | | √ | |
| 2.Cosmetic Inspection | | | | | |
| 433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin | | Visual check | | √ | |
| Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × <input type="checkbox"/> measurement judgment, record data. | | | | | |
| Final judgment (pass/fail) | pass | | | | |
| Non-conformity treatment | | | | | |
| Inspected by: | Checked by: | | | | |
| Date: 2023-11-27 | Date: | | | | |