

# Inspection Record Report

Part Number & Part Name: LHE6118

Inspection referred document: LHE6118检验文件

Inspection time: 2023-11-27

Inspection step:

Inspection item	Inspection/Testing Criteria	Inspection method	Inspection result	Judgment	Remark
<b>1.Cosmetic Inspection</b>					
Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap.		Visual check		√	
<b>2.Cosmetic Inspection</b>					
433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin		Visual check		√	
Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × <input type="checkbox"/> measurement judgment, record data.					
Final judgment (pass/fail)	pass				
Non-conformity treatment					
Inspected by:	Checked by: 3				
Date: 2023-11-27	Date: 2023-11-27				