

Inspection Record Report

Part Number & Part Name: LHE6118

Inspection referred document: LHE6118检验文件

Inspection time: 2023-11-27

Inspection step:

Inspection item	Inspection/Testing Criteria	Inspection method	Inspection result	Judgment	Remark
1.Cosmetic Inspection					
Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap.		Visual check		√	仪器分类.txt
433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin		Visual check		√	20231117-10493 2.png
Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × <input type="checkbox"/> measurement judgment, record data.					
Final judgment (pass/fail)	pass				
Non-conformity treatment					
Inspected by:	Checked by: 3				
Date: 2023-11-27	Date: 2023-11-27				

attach file: 仪器分类.txt

1. 61MWD

LHE6116

LHE6118 125°C

LHE6118B 150°C

LHE6118C 150°C

LHE6716 高温直井短接

2. 温高压MWD

LHE5618C 175°C 双175MWD

3. 475近钻头

LHE7611A/LHE7612A LHE7611C/LHE7612C

4. 675近钻头

LHE7611B/LHE7612B LHE7611G/LHE7612G

无线发射短节

LHE7613B

5. 电阻率

LHE7430B

6. 旋转阀

LHE5616C 旋转脉冲发生器

LHE5616B 175°C/172MPa 5.25高排转阀

7. 陀螺测斜仪

8. 伽马探管

LHE6117

9. 150°C转换短节

LHE6126B

10. 工程参数

LHE6151



attach file: 20231117-104932.png