

Inspection Record Report

Part Number & Part Name: LHE6118

Inspection referred document: LHE6118检验文件

Inspection time: 2023-11-27

Inspection step: In stock

Inspection item	Inspection/Testing Criteria	Inspection method	Inspection result	Judgment	Remark
1.Cosmetic Inspection					
Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap.		Visual check		√	20231117-10493 2. png
433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin		Visual check		√	
2.Connection check					
The SMA plugconnected to the SMA socket normally		Visual check		√	
Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × ⊙ measurement judgment, record data.					
Final judgment (pass/fail)	pass				
Non-conformity treatment					

Inspected by: 李俊杉

Checked by:

Date: 2023-11-27

Date:

纳税信用级别证明

(22)京税信 00033590

企业名称: 北京六合伟业科技股份有限公司

社会信用代码/识别号: 9111010675526336XD

法定代表人: 冯建宇

登记注册类型: 私营股份有限公司

经营地址: 北京市丰台区南四环西路188号12区39号楼(园区)

经“国家税务总局北京市税务局电子税务局”查询,该企业 2022 年度信用级别

评定为: **A 级**

特此证明!

税务机关(签章)

2023年08月28日



attach file: 20231117-104932.png