

Inspection Record Report

Part Number & Part Name: LHE6118检验文件

Inspection referred document: LHE6118检验文件

Inspection time: 2023-11-27

Inspection step: In stock

| Inspection item | Inspection/Testing Criteria | Inspection method | Inspection result | Judgment | Remark |
|---|-----------------------------|-------------------|-------------------|----------|--------------------------|
| 1.Cosmetic Inspection | | | | | |
| Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap. | | Visual check | | √ | 20231117-10493 2. png |
| 433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin | | Visual check | | √ | |
| 2.Connection check | | | | | |
| The SMA plugconnected to the SMA socket normally | | Visual check | | √ | |
| Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × ⊙ measurement judgment, record data. | | | | | |
| Final judgment (pass/fail) | pass | | | | |
| Non-conformity treatment | | | | | |

Inspected by: 李俊杉

Checked by: 3

Date: 2023-11-27

Date: 2023-11-28

纳税信用级别证明

(22)京税信 00033590

企业名称: 北京六合伟业科技股份有限公司
社会信用代码/识别号: 9111010675526336XD
法定代表人: 冯建宇
登记注册类型: 私营股份有限公司
经营地址: 北京市丰台区南四环西路188号12区39号楼(园区)
经“国家税务总局北京市税务局电子税务局”查询,该企业 2022 年度信用级别

评定为: **A 级**

特此证明!

税务机关(签章)

2023年09月28日



attach file: 20231117-104932.png