

Inspection Record Report

Part Number & Part Name: LHE6118检验文件

Inspection referred document: LHE6118检验文件

Inspection time: 2024-01-03

Inspection step:

Inspection item	Inspection/Testing Criteria	Inspection method	Inspection result	Judgment	Remark
1.Cosmetic Inspection					
Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap.		Visual check	中文	√	
433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin		Visual check			
2.Connection check					
The SMA plugconnected to the SMA socket normally		Visual check			
Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × ⊙ measurement judgment, record data.					
Final judgment (pass/fail)					
Non-conformity treatment					

Inspected by:	Checked by: 3	
Date: 2024-01-03	Date: 2024-01-03	