

Inspection Record Report

Part Number & Part Name: LHE6118检验文件

Inspection referred document: LHE6118检验文件

Inspection time: 2024-01-03

Inspection step: In stock

| Inspection item | Inspection/Testing Criteria | Inspection method | Inspection result | Judgment | Remark |
|---|-----------------------------|-------------------|-------------------|----------|--------|
| 1.Cosmetic Inspection | | | | | |
| Product ID marking is clear, no serious scratches, damaged,corrosion on the surface; no obvious gap. | | Visual check | en | √ | |
| 433MHz antenna wrapped with red heat shrink tube; The SMA joint is the female pin | | Visual check | | √ | |
| 2.Connection check | | | | | |
| The SMA plugconnected to the SMA socket normally | | Visual check | | √ | |
| Remark: <input type="checkbox"/> Attribute judgment, pass √, fail × ⊙ measurement judgment, record data. | | | | | |
| Final judgment (pass/fail) | | | | | |
| Non-conformity treatment | | | | | |

| | | |
|------------------|-------------|--|
| Inspected by: 1 | Checked by: | |
| Date: 2024-01-03 | Date: | |